



State Water Resources Control Board

January 11, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 5142

Battalion Chief Andrew Wordin Office of the Fire Marshal Fire Prevention Bureau 200 North Main Street, 17th Floor Los Angeles, CA 90012 andrew.wordin@lacity.org

SUBJECT:

FAILURE TO COMPLY; UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT LOS ANGELES CITY FIRE STATION # 112, 444 SOUTH HARBOR BOULEVARD, SAN PEDRO

Dear Chief Wordin:

As of the date of this letter, the State Water Resources Control Board (State Water Board) has not received a response to our November 5, 2015 Notice of Violation (NOV)(attached). You are directed to correct the ongoing violations identified in the NOV and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within ten (10) days from the date of this letter.

Please send all compliance documentation to the following:

State Water Board

Ms. Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16th Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

Local CUPA

Mr. Aaron Mungaray
Fire Inspector
Los Angeles City Fire Department
200 Main Street, Suite 1700
Los Angeles, California 90012
aaron.mungaray@lacity.org

Failure to comply with this notice may result in an enforcement action by the State Water Board. The State Water Board reserves the right to bring an action against the owner and/or operator of the tank(s) in violation, or it may recommend that the Los Angeles City Fire Department pursue enforcement, or the Los Angeles City Fire Department may elect to pursue enforcement independently.

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

FELICIA MARCUS, CHAIR | THOMAS HOWARD, EXECUTIVE DIRECTOR

If you have any questions, please contact me at (916) 341-5551, or by email at Amantha. Henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

UST Enforcement Unit

Office of Enforcement

Attachment: November 5, 2015 Notice of Violation

cc: (via email only)

Ms. Anna Olekszyk
Acting CUPA Manager
Los Angeles City Fire Department
anna.olekszyk@lacity.org

Battalion Chief Curt Klafta Los Angeles City Fire Department curt.klafta@lacity.org

Captain Dan Dragotto
Los Angeles City Fire Department
daniel.dragotto@lacity.org

Mr. Aaron Mungaray
Fire Inspector
Los Angeles City Fire Department
aaron.mungaray@lacity.org

Mr. Steve Hillman General Services Department City of Los Angeles steve.hillman@lacity.org

Mr. Sean Sullivan
General Services Department
City of Los Angeles
sean.sullivan@lacity.org

Mr. Joshua Muncie General Services Department City of Los Angeles joshua.muncie@lacity.org





State Water Resources Control Board

November 5, 2015

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 0640 0006 0950 4322

Chief Curt Klafta
Los Angeles City Fire Department
Underground Storage Tank Unit
200 North Main Street, Suite 1700
Los Angeles, California 90012
curt.klafta@lacity.org

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS

LOCATED AT LOS ANGELES CITY FIRE STATION # 48, 444 SOUTH HARBOR

BOULEVARD, SAN PEDRO

Dear Chief Klafta:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on October 22, 2015, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Operating Permit – The facility permit to operate is expired.	All	October 22, 2015	Ongoing	H&SC 25284(a)
2	Failure to Maintain Facility and Tank Information (A&B Forms) – Tank form B in CERS has not been approved by the CUPA and was not onsite at the time of inspection. The form contains errors and needs to be updated to include: correct number of tanks, correct number of compartments in the tank, drop tube shutoff valve and not ball float, strike plate if applicable, correct piping system type, method of corrosion protection and verify the installation date.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)

No.	Violation	Tank	Start Date	Stop Date	Regulation
3	Failure to Maintain Monitoring Plan – The monitoring plan was not onsite at the time of inspection. The document in CERS has not been approved by the CUPA. The plan contains errors and needs to be updated to include: automatic tank gauging, no line leak detectors, and edit the recordkeeping section for accuracy.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)(9)
4	Failure to Submit or Update Plot Plan/Site Map – The site plan in CERS is incomplete and has not been approved by the CUPA. It does not identify monitoring equipment or a scaled diagram which indicates the location of the UST systems with respect to buildings or other landmarks.	All	October 22, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)(8)
5	Failure to Maintain Response Plan Onsite – The response plan was not onsite at the time of inspection. The document in CERS has not been approved by the CUPA.	All	October 22, 2015	Ongoing	23 CCR 2712(i)
6	Failure to Notify Local Agency of DO – The owner statement of designated UST operator form in CERS is not signed.	All	October 22, 2015	Ongoing	23 CCR 2715(a)
7	Failure to Monitor Product Piping – The sensor in the fill sump is unable to detect a leak at the earliest opportunity because it is on the wrong side of the sump. The sensor in the UDC is unable to detect a leak at the earliest opportunity because it is raised approximately one inch off the bottom of the dispenser pan. Sensors must be located at the lowest point in the sump, directly beneath product piping.	All	October 22, 2015	Ongoing	23 CCR 2630(d)
8	Failure to Maintain Secondary Containment – The secondary containment test conducted on June 11, 2015, reported a failure to the under dispenser containment (UDC). The UDC is not capable of storing hazardous substance. The bottom of the UDC is rusted out.	Dispen ser	June 11, 2015	Ongoing	H&SC 25291(a)(2)
9	Failure to Meet Spill Containment Requirements— The spill containers had liquid inside of them which prevents their ability to hold five gallons. Liquid was removed at the time of inspection.	All	October 22, 2015	October 22, 2015	23 CCR 2635(b)(1)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Ms. Rebecca Green
UST Enforcement Unit
State Water Resources Control Board
1001 I Street, 19th Floor
Sacramento, California 95814
rebecca green@waterboards.ca.gov

Local CUPA

Mr. Aaron Mungaray
Fire Inspector I
Los Angeles City Fire Department
200 Main Street, Suite 1700
Los Angeles, California 90012
aaron.mungaray@lacity.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel Senior Environmental Scientist UST Enforcement Unit

cc: See next page.

Office of Enforcement

cc: (via email only)

Ms. Anna Olekszyk Acting CUPA Manager Los Angeles City Fire Department anna.olekszyk@lacity.org

Captain Dan Dragotto Los Angeles City Fire Department daniel.dragotto@lacity.org

Mr. Aaron Mungaray
Fire Inspector I
Los Angeles City Fire Department
aaron.mungaray@lacity.org

Mr. Sean Sullivan
General Services Department
City of Los Angeles
sean.sullivan@lacity.org





State Water Resources Control Board

November 30, 2015

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7014 2120 0003 7566 7289

Battalion Chief Curt Klafta Underground Storage Tank Unit Los Angeles City Fire Department 200 North Main Street, Suite 1700 Los Angeles, California 90012 curt.klafta@lacity.org

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT FIRE STATION # 112, 444 SOUTH HARBOR BOULEVARD,

SAN PEDRO

Dear Chief Klafta:

In our November 5, 2015 Notice of Violation (NOV) letter, Fire Station #112 was incorrectly listed as Fire Station #48. The State Water Resources Control Board acknowledges that Fire Station #112 has received the NOV and is working to correct the violations found during the October 22, 2015 Underground Storage Tank inspection. Thank you for your cooperation.

Sincerely,

Amantha Henkel Senior Environmental Scientist UST Enforcement Unit

Office of Enforcement

cc: See next page.

cc: (via email only)

Ms. Anna Olekszyk Acting CUPA Manager Los Angeles City Fire Department anna.olekszyk@lacity.org

Cpt. Dan Dragotto Los Angeles City Fire Department daniel.dragotto@lacity.org

Mr. Aaron Mungaray Los Angeles City Fire Department aaron.mungaray@lacity.org

Mr. Sean Sullivan
General Services Department
City of Los Angeles
sean.sullivan@lacity.org